

COPIES RECEIVED	
DISTRIBUTION	
STATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICE OF REPORTS ON WELLS</p> <p>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PROTEST (Form C-101) FOR SUCH PROPOSALS.</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>6. Name of Operator Anadarko Hess Corporation</p>		<p>7. Unit Agreement Name</p>
<p>8. Address of Operator Drawer "D", Monument, New Mexico 88265</p>		<p>8. Farm or Lease Name Tulk "B" - State</p>
<p>9. Location of Well UNIT LETTER <u>E</u> <u>2222.9</u> FEET FROM THE <u>North</u> <u>660</u> LINE AND FEET FROM <u>West</u> <u>5</u> <u>15S</u> <u>32E</u> TOWNSHIP RANGE NMPM.</p>		<p>9. Well No. <u>1</u></p>
<p>10. Elevation (Show whether DF, RT, GR, etc.) <u>4329' DF</u></p>		<p>10. Field and Pool, or Wildcat Tulk Wolfcamp</p>
<p>11. County <u>Lea</u></p>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>		<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANT <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	
---	--	--	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted 30 sx. cement plug in OH from 9561' to 9730'. Cut and pulled 5-1/2" casing from 4320'. Spotted 25 sx. cement plug in and out 5-1/2" casing from 4370' to 4265', and 25 sx. cement plug in OH 3870' to 3945'. Spotted 25 sx. cement plug in and out 8-5/8" casing at 3915'. Cut and pulled 8-5/8" casing from 995'. Spotted 30 sx. plug from 1030' to 975' & 35 sx. cement plug from 401' to 356'. Spotted 10 sx. plug in top of 13-3/8" casing. Installed dry hole marker. Well P&A.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan TITLE Area Superintendent DATE 10-18-74

APPROVED BY John W. Runyan TITLE Geologist DATE 10-18-74

CONDITIONS OF APPROVAL, IF ANY: