

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE PLAN NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

Modified Form No.

ND60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC-029406(B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Grace Mitchell "B"

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Maljamar Grbg SA

11. SEC., T., R., W., OR BLK. AND
SURVEY OR AREA

Sec. 5-T17S-R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER WIW

2. NAME OF OPERATOR Marbob Energy Corporation 3a. Area Code & Phone No. (505) 748-3303

3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1980 FSL 1980 FEL
Unit 8

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4103' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Return to active injection

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

We propose to put back on active injection as follows:

RIH w/overshot and pull pkr. RIH w/3 3/4" bit and clean out csg to 4085' PBTD. RIH w/2 3/8" plastic coated tbq and new 4 1/2 R-4 pkr and set pkr at 3850'. Circ. pkr fluid. Test csg to 500# for 30 minutes. Put back on injection.

RECEIVED
APR 9 8 21 AM '90
CARBONATE AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED

Rhonda Nelson TITLE Production Clerk

DATE April 2, 1990

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval
by State

*See Instructions on Reverse Side