Form 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED	
Budget Bureau No. 1004-013:	4
Expires: March 3 1 1993	

Expires: March 3 1,1993

5. Lease Designation and Seriai No.

LC 029509B

7. If Unit or CA, Agreement Designation

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

6. If Indian, Allonee or Tribe Name

SUBMIT IN TR			
Type of Well		8920003410	
Oil Gas Well Other Injection		8. Well Name and No.	
2. Name of Operator		MCA Unit, Well # 100	
Conoco Inc	·	9. API Well No.	
3. Address and Telephone No.		30-025-08041	
10 DESTA DR. STE. 100W, MIDLAND, TX. 7	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T. R. M. or Survey Description)	Maljamar Grayburg/SA		
		11. County or Parish, State	
660' FSL & 660' FEL, Sec. 19,			
	Lea		
TIN CHECK APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment Recompletion	Change of Plans New Construction	
Subsequent Repon	Plugging Back Casing Repair	Non-Routine Fractunng Water Shut-Off Conversion to Injection	
Final Abandonment Notice	Other Casing Integrity Test	Dispose Water INole: Reponresuitsof multiplecompitiononWdf Completion or Recompletion Report and Log form.)	
Describe Proposed or Completed Operations (Clearly state all pertinengive subsurface locations and measured and true vertical depth.)	at details, and give pertinent dates, including estimated date of star as for all markers and zones pertinent to this work.)*	ting any proposed work. If well is directionally drilled	

It is proposed to perform a casing integrity test on the well in preparation for requesting temporary abandonment approval. The following procedure will be followed:

- 1. POOH with production equipment.
- 2. Set a plug within 100' of the top perf.
- 3. Notify the BLM 24 hours before pressure tesing casing to 500 psi for 30 minutes.
- 4. RIH with tubing and circulate packer fluid.
- 5. POOH with tubing and fill hole with packer fluid.

When completed, a successful pressure test will be	e submitted with a reason a	ind a request to temporarily abandon th	is well.
		PETER W. CHESTER	The state of the s
		APR 2 8 1999	
		ROSWELL RESOURCE	
14. I hereby certify that the foregoing is true and correct	Bill R. Keathly	ROSWELL RESOURCE AREA	4-15-99
Signed Deel & Lacully	Title Sr. Regulatory S	pecialist Date -	4-13-33
(This space for Federai or State office use)			
Approved by Conditions of approval if any:	Title	Date	
BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FIL	E ROOM		Condulant statements
Title 18 U.S.C. Section 1001, makes it a crime for any person know	ingly and willfully to make to any de	partment or agency of the United States any false, fict	INDUS OF TRANSMERK STATEMENTS

or representations as to any matter within its junsdiction.



9 9 - 1 20