

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLA
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Ing. Well temp. Shut-in</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-029405(B)</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	7. UNIT AGREEMENT NAME <u>MCA</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>Unit P</u>	8. FARM OR LEASE NAME <u>MCA Unit Bty 1</u>
14. PERMIT NO. <u>660' FSL & 660' FEL</u> <u>30-025-08041</u>	9. WELL NO. <u>100</u>
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT <u>Malamar 6/SA</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 19-17S-32E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>CMT sq 2 Csq Shoe</u>	☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU on 8/27/85, Rel pkr @ 3399'
- ② Pumped 70 bbls 10# brine down 4 1/2" csg
- ③ Dropped 1 1/2 yds Pea Gravel down 4 1/2" & run csg scraper to 3520'
- ④ Pumped 50 sxs class "c" cmt w/.6% Halad-4 & 2% CaCl₂
- ⑤ Tagged top of cmt @ 3496', Drill out to 3580'
- ⑥ Circ. hole clean. Pumped 105 bbls 15% HCL acid, flushed w/22 bbls TFW
- ⑦ Set pkr @ 3500' and return to injection
- ⑧ Rigged down on 9/21/85

ACCEPTED FOR RECORD

JWD

JAN 16 1986

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Ken L. Long

TITLE

Administrative Supervisor

DATE

1-14-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval
by State

*See Instructions on Reverse Side

RECEIVED
JAN 17 1986
O.C.D.
HOBBS OFFICE