

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Expires August 31, 1985

P. O. Box 460
HOBBS, NEW MEXICO 88240

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection well</u>	7. UNIT AGREEMENT NAME <u>MCA</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	8. FARM OR LEASE NAME <u>MCA Unit</u>
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	9. WELL NO. <u>331</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>Unit D</u>	10. FIELD AND POOL, OR WILDCAT <u>Maljamar 6/5A</u>
14. PERMIT NO. <u>30-025-08501</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 20-17S-32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MRU on 1-28-86, Killed well w/ 15 bbls 2% KCL TFW
- ② Pmp'd 40 bbls brine down +bg. Tag fill @ 3625'. CO to 4035'. Circ. sand out of hole from 4035' - 4110' (PBTB)
- ③ Establish pump-in rate. Set RBP @ 3518'. Press. test csq to 500 psi, held OK
- ④ Dump 1 x sand on RBP & set pkr @ 863'. Press. test backside to 500 psi.
- ⑤ Pumped tracer material and traced to 791'. (Shoe @ 767')
- ⑥ Repaired waterflow w/ 20 bbls Flo-Chek and 150 sxs class "H" cmt w/ 3% CaCl₂
- ⑦ Poot w/ pkr. Circ. sand off RBP and Poot w/ RBP. With w/ Baker pkr & set @ 3510'. Press. test csq to 500 psi.
- ⑧ Circ. pkr fluid. Press. test backside to 500 psi and held OK.
- ⑨ Rigged down on 2-8-86

ACCEPTED FOR RECORD
FEB 19 1986

18. I hereby certify that the foregoing is true and correct

CARLSBAD, NEW MEXICO

SIGNED [Signature]

TITLE

Administrative Supervisor

DATE

2-13-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval
by State

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Petro-Lewis (1) Cities (1) File

RECEIVED
FEB 24 1986
C.C.D.
HOBBS OFFICE