

(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029405 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

0 JICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 1980' FWL of Sec. 20

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,988' DF

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit Bt. 1

9. WELL NO.

23

10. FIELD AND POOL, OR WILDCAT

Maly. B-SA Refract

11. SEC., T., R., M., OR BLE, AND
SURVEY OR AREA

Sec. 20, T-17S R-32E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

got washed and cleaned out 4,000'-4,041'. Spent 200 gals.
28% HCl acid at 3,901'. Set str. & acidized w/800 gals. acid.
Set str. @ 3,564' & treated w/500 gals. 15% HCL-NE acid,
1500 gals. treated fresh water. Traced w/15,000 gals. treated fresh
water & 30,000* sand. Cleaned out & drilled BP to 3,957'.
Drilled BH BP 4,060'-4,073'. Ran 3 1/2" tubing, set at 3,991'.
Placed well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Gault

TITLE

Division Office Manager

DATE

1-21-74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

USBS-5, MCA-3, File

