

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029405 B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA UNIT 141

9. WELL NO.

95

10. FIELD AND POOL, OR WILDCAT

Malj. GSA Repress

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 20, T-17 S, R-32 E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

☒ GAS WELL ☐ OTHER

NAME OF OPERATOR

CONTINENTAL OIL COMPANY

ADDRESS OF OPERATOR

Box 460, Hobbs, New Mexico 88240

LOCATION OF WELL (Report location clearly, and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL & 1980' FEL OF Sec 20.

PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3977 DF

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

IT IS Proposed to CO & Acidize the well as follows:
CO to 4036'. Run T69 & Set OH Pkr AT 3900' & Treat w/ 1000
Gals 28% Acid. Set OH Bridge Plug AT 3890'. Plug
Back IN open Hole to 3900' w/ Pkg Gravel and Sand, Treat
w/ 1500 Gals 15% Acid with Additives. Flush with
Treated Fresh Water, Drill out and/or Push to Bottom
the open Hole Bridge Plug. Re-run Producing Equipment
& Return to Production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Bill Penbow

TITLE

adm. supervisor

DATE

9-16-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

SEP 17 1976

BERNARD MOROZ

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

USSS-5, MCA 4, File