

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029405 (6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit Bty 1

9. WELL NO.

98

10. FIELD AND POOL, OR WILDCAT

Mag. G-5A Region

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 20, T-17S R-32E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 460, Hobbs New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FSL &amp; 660' FWL of SEC. 20

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3953' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

Cleaned out & jet washed to T.D. 4013'. Set OH BP at 3833' w/13'  
by sand on top. Set OH Pbr. at 3721' & acid fraced w/500 gals.  
15% acid and 2500 gals 28% acid. Plugged back w/gravel  
to 3705' & set OH Pbr. at 3620'. Fraced OH with 15,000  
gals. Wtr. and 30,000<sup>st</sup> sand. Cleaned out to T.D. 4,013'.  
Ran producing equipment and placed well back  
on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Gault

TITLE

Division Office Manager

DATE

11-14-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD  
NOV 16 1973U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

\*See Instructions on Reverse Side

USGS-6; MCG-3, File