Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobba, NM 88240

OIL CONSERVATION DIVISION

WELL API NO.	
30-025-0857/8	
5. Indicate Type of Lease	
STATE	FFF XX

1.0. Box 1980, 10008, NM 88240	P.O. Box 20	188	WELL API NO.	1
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico			
	,		5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease	NO FEE XX
OUNDDW/				110.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT HESERVOI	IH. USE "APPLICATION FOR PE	RMIT	7. Lease Name or Unit A	greement Name
(FORM C-101) 1. Type of Well:) FOR SUCH PROPOSALS.)			
OIL GAS WELL X				
2. Name of Operator	OTHER	Simmons Witt ASL		
YATES PETROLEUM CORPORATI	ON		8. Well No.	
Address of Operator 105 South 4th St., Artesia, NM 88210 9. Pool na		9. Pool name or Wildcat		
4. Well Location	a, NM 88210			Morrow
Unit Letter J :2310_	Ewe m South	2000		
- : <u>- : - : - : - : - : - : - : - : - :</u>	reet From The SOUTH	Line and 2080	Feet From The	East Line
Section 11.	Township 16S Ra	unge 35E N	TAGYING Ton	
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	IMPM Lea	County
		0' GR		
11. Check App	ropriate Box to Indicate 1	Nature of Notice, Re	port, or Other Data	
NOTICE OF INTEN	TION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	f	ING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	()	
PULL OR ALTER CASING		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB		
OTHER:		D.		
12 D				<u>x</u>
 Describe Proposed or Completed Operations (work) SEE RULE 1103. 	Clearly state all pertinent details, and	d give pertinent dates, includin	ng estimated date of starting	any proposed
4-22-98 - Bladed road and	scraped off pad.	Dug out collar	Domorro d. Jan. 1	1 1 6
ro o/o casing.				
4-23-98 - Welded on 13-3/	8" X 13-5/8" 3000# :	starting head.	Built new cella	r and backfillod
see anenors and dug works	ver prt.			r and backinited
4-24-98 - Prep to move in	re-entry equipment	•		
4-25/27-98 - Moved in and	rigged up pulling u	unit and re-entr	y equipment. N	ippled up 12" 90
BOP. Notified OCD-Hobbs a	and Nancy Wall with	the FAA of inter	nt to spud.	
4-28-98 - Tested blind randrill collars, 6-5/8" reg	Y 3-1/2" areassure	1500 psi. Rigge	d up swivel. T	IH with 4-3/4"
surface plug at 9:40 AM 4-	-27-98 Fell out of	and 12-1/4" mil.	I tooth bit. Sp	pudded on
not tag plug at 310' (no p	olug). Washed down	from 363-567!	Tagged obut	
12-1/4" bit. TIH with 7-	7/8" bit, collars ar	nd tubing. Tagg	lagged Stup. I	rooH with
grigged up swiver. forquit	ng and bouncing 1st	15', then smooth	hed out. TIH fr	rom 813-840'
Washed down to 1040'.				
I hereby certify that the information above to true and cos	mplete to the best of my knowledge and be	eliaf. COI	NTINUED ON NEXT	PAGE:
SHONATURE JUSTY ILLE		Operations Tec	hnician DATE	April 29, 1998
TYPEOR PRINT NAME Rusty Klein			TELEP	THONE NO. 505/748-14
	CHAIR A CAMS			
(This space for State Use) ORIGINAL & GALLE	H. SHI KVISOF			y "ja
APPROVED BY	mre			e de la companya de l

CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION Simmons Witt ASL #1 Section 11-T16S-R35E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

4-29-98 - TOOH with 7-7/8" bit. TIH with 10-1/2" OD skirted dress off mill, drill collars and tubing. Tagged stub. Cut over and start milling. Milled off 3' to 570'. TOOH. Rigged up casing crew. TIH with 583' of 13-3/8" 32# J-55 casing with 10-1/2" OD slip joint. Tagged stub and rotated 1/4 round. Slipped over stub 3' cutoff. Nippled down BOP and set slips. Installed 13-5/8" 5K X 11" 3K spool. Nippled up BOP. TIH with 7-7/8" bit, drill collars and tubing.

Rusty Klein

Operations Technician

April 29, 1998