

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-12583
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Schenck ATP
8. Well No.	1
9. Pool name or Wildcat	Big Dog Strawn, South
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3988' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter D : 660 Feet From The North Line and 608 Feet From The West Line

Section 11 Township 16S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3988' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Spud on re-entry ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-30-99 - Scraped off pad. Removed dry bole marker. Dig out cellar. Cut off 8-5/8". Installed 8-5/8" X 11" 5000 starting head.

12-31-99 - Set anchors. Moved in and rigged up pulling unit and re-entry equipment.

NOTE: Notified Hobbs of intent to spud on 1-3-2000.

1-1-3-2000 - Shut down for New Year's holiday.

1-4-2000 - Nippled up 10" 5000# hydraulic BOP. Installed 3" return line to shale shaker.

TIH with 7-7/8" mill tooth bit and drill collars. Drilled on surface plug (10' of cement).

Drilled stringers for 15'. Lost 50 bbls when fell out of cement. Caught circulation.

TIH with drill collars. Changed out stripper rubber to 2-7/8". Picked up 1 joint of drillpipe.

Shut down due to high winds. NOTE: Spudded in at 12:00 noon 1-3-2000.

1-5-2000 - Picked up drillpipe. TIH and tagged up at 1160'. Rigged up swivel. Washed

down and drilled to 1250'. Fell out. Washed down to 1310'. Laid down swivel. TIH to

4723'. No plug at shoe. Circulated and conditioned mud. TIH and tagged plug at 6190'.

Drilled to 6215'. TIH to 6291'. Circulate and condition mud. TIH - did not tag plug at

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Jan. 13, 2000

TYPE OR PRINT NAME Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: