

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

Oct 15 8 43 AM '65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Schenck, Markham, Cone	8. Farm or Lease Name Schenck A
3. Address of Operator	9. Well No. 1-4
4. Location of Well UNIT LIEFER D , 360 FEET FROM THE North LINE AND 658 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 16 RANGE 35 NMPM.	10. Field and Pool, or Wildcat Townsend-Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot a 25 sx plug to cover all perforations
2. Load hole w/mud laden fluid
3. Spot a 25 sx plug at stub of 5 1/2" casing
4. Spot a 25 sx plug at 8076'
5. Spot a 25 sx plug at 7337'
6. Spot a 25 sx plug at 6180'
7. Spot a 25 sx plug at base of 8 5/8" 4646'
8. Spot a 10 sx plug in top and erect a regulation marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Hobbs Pipe & Supply Co.

SIGNED [Signature] TITLE **Assistant Manager** DATE **10/14/65**

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: