

(May 1963)

DEPARTMENT OF THE INTERIOR

(Other instructions on reverse side)

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. <i>12-039415 (A)</i>
2. NAME OF OPERATOR <i>Continental Oil Company</i>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <i>P.O. Box 460, Hobbs, N.M. 88240</i>		7. UNIT AGREEMENT NAME <i>MCA Unit</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>2610' FSL + 2640' FEL of Sec. 19, T-17S, R-32E, Lea Co., N.M.</i>		8. FARM OR LEASE NAME <i>MCA Unit</i>
14. PERMIT NO.		9. WELL NO. <i>58</i>
15. ELEVATIONS (Show whether DF, RT, CR, etc.) <i>3936' DF</i>		10. FIELD AND POOL, OR WILDCAT <i>MCA, G-5A, Lea Co.</i>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec. 19, T-17S, R-32E</i>
		12. COUNTY OR PARISH <i>Lea</i>
		13. STATE <i>N.M.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☒SHOOT OR ACIDIZE ☒REPAIR WELL ☐(Other) *Deepen 46' & Stimulate*PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐*Deepen 46' & Stimulate* ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

I am proposed to stimulate OH 3480'-3750' w/sand-wtr frac: 45,000# 20-40 sand in 30,000 gal gelled prod. wtr. Drill out 46' to new TD 4016'. Stimulate OH 3880-4016 w/6000 gals 15 PC. LSTNE 6X retarded acid. Run prod equipment. Place well back on prod.

18. I hereby certify that the foregoing is true and correct

SIGNED *J. E. Gentry*TITLE *Administrative*DATE *1-29-71*

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*4565 (5) MCA(3) File***APPROVED**

FEB 1 1971

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side