

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruction on re-
verse side)

Form approved:
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection</u>	N. M. OIL CONS. COMMISSION P. O. BOX 1980 HOBBS, NEW MEXICO 88240	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-029405(6)</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>		8. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>		7. UNIT AGREEMENT NAME <u>MCA Unit</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>2615' FSL & 25' FWL</u>		8. FARM OR LEASE NAME <u>MCA Unit</u>
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, RT, GR, etc.)	9. WELL NO. <u>61</u>
		10. FIELD AND POOL, OR WILDCAT <u>Maljamar G/SA</u>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec 20-17S-32E</u>
		12. COUNTY OR PARISH <u>Lea</u>
		13. STATE <u>NM</u>

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Conv. to cased hole

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Dump 390 sxs oyster shells down csg. Tag @ 3323'. CO 40' bridge of shells. Spot 100# cal-seal on top of shells. Set ptr @ 3323'. Pmpd 20 sxs class "C" cmt w/ 2% CaCl₂ & 30 sxs class "H" thixotropic. Flush w/21 bbls 2% KCL. TOC @ 3473'. Drill to 3580' & fell thru. CO oyster shells from 3590'-3695'. Drill 4' bridge & fell to 3695'. CO to 4018'. Jet wash 3882'-3903' & 3923'-3977'. Pmpd 23 bbls 15% HCL acid & circ out w/161 bbls 2% filtered KCL. Chemically inhibit. Spot 37 bbls 15% HCL acid. Flush tbg w/23 bbls 2% filtered KCL. Circ hole w/233 bbls 8.4# filtered KCL. Pmpd 50 bbls Hydrocon E slurry & flush w/15 bbls filtered KCL. Tag puddle pack @ 3618'. Mix add'l. 15 bbls Hydrocon E. Circ. wellbore w/116 bbls filtered 2% KCL. Drill from 3460'-3465'. Tag hydrocon @ 3465'. DO to 4018'. Underream from 3560'-3850'. Circ. hole clean. Run liner w/TOL @ 3226'. Set down on hanger packer. Pmpd 150 sxs 50/50 poz mix class "C" w/ 3/4% HALAD 4. Displace cmt w/28 BW. Set hanger ptr. Set RBP @ 3200'. Hole betw. 105' & 120'. Packing leaking betw 7" & 10 3/4". Poured 2 sxs sand on RBP. Pmpd 75 sxs class "C" cmt w/4% CaCl₂. Displace w/2 BFW. TOC @ 75'. DO to 125' & fell thru. Rel RBP. TOC @ 3875'. DO cmt to 4017'. Ran logs from 4014'-3150'. TOC @ 346' Perf w/1 JSPF from 4005'-3890'

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Administrative Supervisor

DATE 5/10/85

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

TITLE

DATE

MAY 14 1985

*See Instructions on Reverse Side

RECEIVED

MAY 20 1985

O.C.D.
HOBBS OFFICE

040019 APT 421510

1211 11

012111 11 1211 11