

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029405-6

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME MCA
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME MCA UNIT
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, New Mexico 88240	9. WELL NO. 61
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2615' FSL : 25' FWL of Sec. 20, T-17S, R-32E, Lea County, N. Mex.	10. FIELD AND POOL, OR WILDCAT Mali G-SA Repress
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR ALTA Sec. 20, T-17S, R-32E
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3942' DF	12. COUNTY OR PARISH Lea
	13. STATE N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to frac this well with explosives by the following procedures.

Clean out to TD if needed. Load hole from 3977' to 3882' with approx. 6,500# of loose explosives. Place canister with approx. 88# of explosives from 3882' to 3877'. Dumped pea gravel in plastic bags from 3877' to 3838'; with another canister filled with approx. 3680 # explosives from 3838' to 3635'. Set pea gravel and cal seal plug to 3460'. After detonation clean out to TD (3177') and place well back on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Yeakley

TITLE Adm. Section Chief

DATE 11-24-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

USGS-5 FILE

MCA Partners

APPROVED

NOV 25 1969

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side