N.M. Oil Corn Division 1625 N. French Dr.

Form	3	160-5
(June	1	990)

UNITED STATES Hobbs, NM 88240 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 3 1 ,1993
Lease Designation and Serial No.

DUKLAU OF I	TAIND MIANAGEMENT	5. Lease Designation and Serial No.
CUMPDY NOTICES	LC 029405B	
SUNDRY NOTICES AND REPORTS ON WELLS		6. If Indian, Allottee or Tribe Name
	Il or to deepen or reentry to a different reservoir.	
USE APPLICATION FO	R PERMIT—" for such proposals	
SUBMIT IN TRIPLICA TE		7. If Unit or CA, Agreement Designation
	THE TRIT GOATE	
t. Type of Well  ☑ Oil ☐ Gas ☐		
Well Well Other		8. Well Name and No.
2. Name of Operator		MCA #64
Conoco Inc		9. API Well No.
<ol> <li>Address and Telephone No.</li> <li>DESTA DR. STE. 100W, MIDLAND,</li> </ol>	30-025-12772	
······································		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage. Sec., T. R. M. or Survey De	scription)	Maljamar Grayburg/SA
26151 ECT & 261011	ENT Con 20 TITE DOZE V	11. County or Parish, State
2013 FSL & 2010 I	FWL, Sec. 20, T17S, R32E, K	
		Lea, NM
Th CHECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
·	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other Casing Integrity Test	Dispose Water
		Note: Report results of multiple completion on We
12 P		Completion or Recompletion Report and Log form
give subsurface locations and measured and true verti	l pertinent details, and give pertinent dates, including estimated date of startir cal depths for all markers and zones pertinent to this work.)*	ng any proposed work. If well is directionally dril
-		
It is amounted to norform a Cooling Integrity To		
approval. The following procedure will be following	est on the above referenced well in preparation for reque	esung temporary abandonment
approval. The following procedure will be following	nowed.	2
1 DOOH submeduation againment 57	e /	
1. POOH w/production equipment 50		S 5.7
2. Set a plug within 100° of the top perf.		
3. Notify the BLM 24 hours before pressure		
4. RIH with tubing and circulate packer flui		in the second of the second o
<ol><li>POOH with tubing and fill hole with pac</li></ol>	ker fluid.	T S
		. ()

When completed, a successful pressure test will be submitted with a reason and request to temporarily abandon this well

14. I hereby certify that the foregoing is true and correct Signed	Reesa R. Wilkes		01/12/00
	Title Sr. Staff Regulatory Assistant		
(This space for Palents of State of Fide use)	Title	Date	2/23/2000
Conditions of approval if any:  (akove display)  BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE R	hange.		727
BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE R	ROOM, MELD		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.



ROSWELL, NM
BLM
BLM
ROSWELL, NM

