

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-057210

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. *MCA Unit, No. 182*

9. API Well No. *30-025-85012*

10. Field and Pool, or Exploratory Area
Maljama (G-5A)

11. County or Parish, State

Lea, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

10 DESTA DRIVE, STE 100 W, MIDLAND, TX 79705 (915) 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2615 FSL & 2950 FEL

Letter, Sect. 27, T17S, R32E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other *Scale Squeeze*
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-14-91 B1H w/ Model R pkr + tbg set at 3777. Loaded + press cog to 500#. Pmp 10 BBLS TC-405 flush w/ 18 BBLS #10 brine. SI 3 hrs. Pmp 8 BBLS flush. Start 2 BBLS/min at 750#. Broke to 4 BBLS/min at 200#. 2nd lines to 400#. Pmp 40 BBLS 15% acid 4 BBLS/min at 150#. Press to 900# after 32 BBLS. Pmp 1500# salt in 20 BBLS gel. 4 BBLS/min at 1300#. Pmp 40 BBLS acid 4 BBLS/min at 1300#. Block action: 3 BBLS/min at 2700#. Broke to: 4 BBLS/min at 2300#. Pmp 750# salt 4.4 BBLS/min at 1900# in 4 BBLS gel. Action: 4.1 BBLS/min at 2300#. Pmp 40 BBLS acid 4.4 BBLS/min at 200#. Pmp 23 BBLS flush 4.2 BBLS/min at 2300#. ISIP 1600#. 5 min 350# 15 min: vac. Load: 190 BBLS. Rig up to swab. Made 2 runs (6 BBLS) swab. Released pkr. Set pkr at 3777. Pmp: 20 BBLS FPW w/ 40# CaCl₂. 20 BBLS FPW pad 20 BBLS FPW w/ 2 drum TH - 7799. 20 BBLS FPW pad. 100 BBLS FPW w/ 100# CaCl₂. 2500# salt in 32 BBLS gel. 10 BBLS fpw pad. 20 BBLS fpw WITH - 7799. 20 BBLS FPW pad. 100 BBLS FPW w/ 150# CaCl₂: Max: 2850# at 5 BBLS/min 1200# Block action. ISIP 1800#. Bled down to 70# Rel pkr. Reset. RD.

14. I hereby certify that the foregoing is true and correct

Signed

Christine A. Neff

Title

ADMIN. ASSISTANT

Date

7-17-91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date