

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO 80240

SUBMIT IN TR
(Other instruct
verse side)
DATE: 00 00

Approved:
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Conoco Inc.
3. ADDRESS OF OPERATOR
P.O. Box 460 - Hobbs, New Mexico 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2530' FNL & 215' FEL - Unit Letter H
14. PERMIT NO.
30-025-85002
15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
LC-029509A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
MCA Unit
8. FARM OR LEASE NAME
MCA Unit Bly 2
9. WELL NO.
41
10. FIELD AND POOL, OR WILDCAT
Maljamar G-SA
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
21-17S-32E
12. COUNTY OR PARISH
Lea
13. STATE
NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒ Frac OH Producer
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and tones pertinent to this work.)

MIRU. POOH w/ rods & pump. Kill well. G1H to 4052' & tag. POOH. G1H w/ csg scraper to 3650'. POOH. G1H w/ "Tornado Frac" charges. Shot 3884'-3899' for total of 12 shots. Last charges in upper OH section. Tag at 3755'. G1H w/ primer cord to 3765'. Set off charge. Tag at 3761'. G1H w/ bit, DC, WS. to 3708' & tag. Est. circ. DO & jet wash OH from 3755'-3775'. G1H w/ "Tornado Frac" charges, shot at 3758'-3851' for 37 shots. Tag at 4010'. G1H w/ tntg pla to 3640' & set. Test backside to 500psi. Frac w/ 366 bbls and 31,164 # 16-30 sand. Flow well. Circ well. Release pki & POOH. G1H. Tag at 3800'. CO & jet wash to 4100'. Circ clean. POOH. Run producing equipment & place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED Carol O. Gaudin
for William W. Baker
(This space for Federal or State office use)

TITLE Administrative Supervisor

DATE April 20, 1989

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD
DATE _____

MAY 5 1989

*See Instructions on Reverse Side

SSS
CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) OXY (1) FPO (1) JEL