NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	· · ·	Supersedes Old C-102 and C-103
	XICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE U.S.G.S.		5a, Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
L		
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR THUSE "APPLICATION FOR PERMIT ~" (PC	REPORTS ON WELLS 0 DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. DRM C-101) FOR SUCH PROPOSALS.)	
I. OIL X GAS OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Union Oil Company Of California 3. Address of Operator		Hume Queen Unit
	7, Box 2010, Hobbs, N.M. 88240	9, Well No.
4. Location of Well	, BOX 2010, RODDS, N.M. 88240	10. Field and Pool, or Wildcat
	THE North LINE AND 660 FEET FROM	Hume Queen
East Line, section 8	OWNSHIP 16-S 34-E NMPM	
	tion (Show whether DF, RT, GR, etc.)	12. County
	4125' KB	Lea
<sup>16.</sup> Check Appropriate Box	To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO:	SUBSEQUEN	T REPORT OF:
		•
PERFORM REMEDIAL WORK PLUG	AND ABANDON REMEDIAL WORK	ALTERING CASING
<b>7</b>	IGE PLANS CASING TEST AND CEMENT JOB	PLOG AND ABANDONMENT [-]
	OTHER	· · · · · · · · · · · · · · · · · · ·
OTHER		
17 Describe Proposed on Completed Operations (Clearly sta		
		estimated date of starting any proposed
work) SEE RULE 1103.	te all pertinent aetalls, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.		estimated date of starting any proposed
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl		
work) SEE RULE 1703. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}$ " casing stub at 1220 Lug at 8-5/8" casing shoe at 3	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl	ug from $3940'-3960'$ . ug at $5\frac{1}{2}$ " casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	lug from $3940'-3960'$ . Lug at $5\frac{1}{2}''$ casing stub at 1220 Lug at 8-5/8'' casing shoe at 3 Lug at surface with marker. laden fluids.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70.	)'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud 6. Well was plugged & abando	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70.	2'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 25 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud 6. Well was plugged & abando	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70.	)'.
<ul> <li>work) SEE RULE 1103.</li> <li>1. Spotted a 25 sx cement pl</li> <li>2. Spotted a 25 sx cement pl</li> <li>3. Spotted a 25 sx cement pl</li> <li>4. Spotted a 10 sx cement pl</li> <li>5. Hole was loaded with mud</li> <li>6. Well was plugged &amp; abando</li> </ul>	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70.	2'.
<ul> <li>work) SEE RULE 1103.</li> <li>1. Spotted a 25 sx cement pl</li> <li>2. Spotted a 25 sx cement pl</li> <li>3. Spotted a 10 sx cement pl</li> <li>4. Spotted a 10 sx cement pl</li> <li>5. Hole was loaded with mud</li> <li>6. Well was plugged &amp; abando</li> </ul> 18. I hereby certify that the information above is true and co signed by Orig. Signed by	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70.	B10'.
work) SEE RULE 1103. 1. Spotted a 25 sx cement pl 2. Spotted a 25 sx cement pl 3. Spotted a 10 sx cement pl 4. Spotted a 10 sx cement pl 5. Hole was loaded with mud 6. Well was plugged & abando 18. I hereby dertify that the information above is true and co signed MMMMM	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70.	2'.
<ul> <li>work) SEE RULE 1103.</li> <li>1. Spotted a 25 sx cement pl</li> <li>2. Spotted a 25 sx cement pl</li> <li>3. Spotted a 10 sx cement pl</li> <li>4. Spotted a 10 sx cement pl</li> <li>5. Hole was loaded with mud</li> <li>6. Well was plugged &amp; abando</li> </ul> 18. I hereby certify that the information above is true and co signed by Orig. Signed by	ug from 3940'-3960'. ug at 5½" casing stub at 1220 ug at 8-5/8" casing shoe at 3 ug at surface with marker. laden fluids. oned on 10-29=70. mplete to the best of my knowledge and belief. <u>Agent</u>	D'. 10'.

ı