

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-20214
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG-6014
7. Lease Name or Unit Agreement Name: Mesa Queen Unit
8. Well No. 12
9. Pool name or Wildcat Mesa Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Xeric Oil & Gas Corporation	
3. Address of Operator P. O. Box 352, Midland, TX 79702	
4. Well Location Unit Letter <u>J</u> <u>1980</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>17</u> Township <u>16S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4355' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit & lay down rods or tubing.
- 2) RU wireline & jet cut 4 1/2" casing @ 600'.
- 3) POOH laying down w/4 1/2" casing .
- 4) RDMO Pulling Unit.
- 5) MIRU Coiled Tubing Unit & circulate hole w/50 bbls mud.
- 6) Spot Plug #1 @ 3400' w/10 sx Class C + 2% CaCl & tag. **ALL PLUGS ARE 255X DR 100'**
- 7) Spot Plug #2 @ 1300' w/25 sx Class C + 2% CaCl & tag. **WHICHEVER IS GREATER**
- 8) Spot Plug #3 @ 50' inside 4 1/2" casing stub & circulate out w/25 sx Class C + 2% CaCl & tag.
- 9) Spot Surface plug @ 100' w/20 sx Class C + 2% CaCl.
- 10) ND wellhead & install dry hole marker. RDMO

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kyle Lewis TITLE Treasurer DATE 10/19/01
Type or print name Kyle Lewis Telephone No. 915-683-3650
(This space for State use)

APPROVED BY _____ TITLE _____ DATE OCT 23 2001
Conditions of approval, if any: