

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION, C.

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUN 6 9 57 AM '66

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>K-959</b>
7. Unit Agreement Name -
8. Farm or Lease Name <b>MOA State</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Mesa-Queen</b>
12. County <b>Lea</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator <b>Shell Oil Company (Western Division)</b>
3. Address of Operator <b>P. O. Box 1509, Midland, Texas 79701</b>
4. Location of Well UNIT LETTER <b>H</b> , <b>1880</b> FEET FROM THE <b>north</b> LINE AND <b>990</b> FEET FROM THE <b>east</b> LINE, SECTION <b>16</b> TOWNSHIP <b>16S</b> RANGE <b>32E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4341' DF</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Proposed Operation: Perforate additional Queen pay.**

1. Pull rods, pump and tubing.
2. Perforate 3408' - 3414' w/1-3/8" JSPF (total 6 holes).
3. Treat w/230 gallons MCA.
4. Run production equipment and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By  
N. W. Harrison N. W. Harrison TITLE Senior Exploitation Engineer DATE June 1, 1966

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: