

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029 410 (B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

So. Maljamar Deep

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 30, T-17-S, R-32-E

12. COUNTY OR PARISH 13. STATE

Lea

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Harvey E. Yates Co., Inc.

3. ADDRESS OF OPERATOR

Suite 1000, Security National Bank Bldg., Roswell, N. M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

330' FSL &amp; 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3883' GR

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Form 9-331 C submitted 7/30/76 proposed to drill to 12,500'. Lost circulation was encountered while drilling at approximately 9800 feet KB. The hole was drilled to a total depth of 10,128' KB. While trying to cement the lost circulation zone, approx. 818 feet of drill pipe was cemented in the hole. An attempt was made to run wash pipe and recover the fish. However, approx. 50 feet of wash pipe was also left in the hole. (Complete details concerning amount, location and condition of cement, pipe, etc. will be submitted later.) We now propose to run approx. 9000 feet of 4 1/2", 10.50 & 11.60#/ft., K-55 new casing and cement with a sufficient volume to bring cement from 9000' to a point within the 8 5/8 inch intermediate casing. An attempt will be made to complete the well in the lower Abo Section @ approx. 8930' to 8960' KB.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Consultant

DATE 10-17-76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

