

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR INFORMATION TO OIL OR GAS PRODUCING WELLS IN A DIFFERENT RESERVOIR.
USE THIS FORM FOR INFORMATION TO OIL OR GAS PRODUCING WELLS IN THE SAME RESERVOIR.)

1. Name of Operator ☐ OIL WELL ☐ GAS WELL ☐ OTHER- **TA Well**

2. Address of Operator **Southland Royalty Company**
1100 Wall Towers West, Midland, TX 79701

3. Location of Well
UNIT LETTER **0** **660** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **31** TOWNSHIP **16-S** RANGE **33-E** N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4241' GR 4253' RT

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
OG-866

7. Unit Agreement Name

8. Name of Lease Home
NE Maljamar Unit

9. Well No.
3

10. Field and Pool, or Wildcat
Undesignated

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-11-78 RUPU. Ran 3 7/8" bit to 10,850', load hole w/brine wtr, POH.
5-12-78 Set CIBP @ 10,830'. Dump 12' cmt 10,818-10,830'.
5-13-78 Perforate 10,404-434', 10,600-608', 10,615-622', 10,648-654',
10,700-710', 10,790-814'.
5-14-78 Acidize w/5000 gal acid. Use 5 stages of 50# benzoic flake, 50#
rock salt on each stage.
5-15-78 Swab, recover load water, rec. trace oil and gas swab dry, POH.
5-19-78 Set CIBP @ 10,450'.
5-20-78 Squeeze perf 10,404-434' w/150 sx Class "H" cmt, reverse out 50 sx.
5-23-78 Test squeeze to 1000#, hold OK. Drlg out BP @ 10,420'.
5-24-78 Acidize overall perf 10,600-10,814' w/3000 gal acid w/100# kenzoic
flake 100# salt.
5-25-78 Swab, rec trace oil.
5-26-78 Perf 10,426-430', swab.
5-27-78 Swab, rec trace oil, 10 BLW, shut in.
5-30-78 Pull tbg, SI, well TA.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Harney Carr TITLE District Engineer DATE 6-21-78

Orig. Signed by John Runyan DATE JUN 26 1978
TITLED Geologist

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY _____

Expired 10/1/76 (2 yr)