

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-061150

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	6. IF INDIAN ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Standard Oil Company of Texas A Division of Chevron Oil Company	7. UNIT AGREEMENT NAME Maljamar (Grayburg) Unit
3. ADDRESS OF OPERATOR 3610 Avenue S, Snyder, Texas 79549	8. FARM OR LEASE NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit, K, 1980' FSL and 1980' FWL of Sec. 10, T-17S, R-32E	9. WELL NO. 59
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT Maljamar (Grayburg-San Andres)
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 4123	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit K, Sec. 10, T-17S, R-32E
	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐
Perforate ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work will commence upon approval.

1. Move in and rig up pulling unit.
2. Pull rods, pump and tubing.
3. Perforate intervals 3856-58, 3904-10, 3938-41, 3949-52, 3995-98 with 2 CJPF.
4. Run tubing, pump and rods and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. W. McFalls

TITLE

District Engineer

DATE

9-19-63

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: