

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION

MAR 24 11 54 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9781
7. Unit Agreement Name
8. Farm or Lease Name State OG
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Test Well
2. Name of Operator Cities Service Oil Company
3. Address of Operator Box 69 - Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER P , 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 30 TOWNSHIP 16S RANGE 37E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3821 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above captioned well was plugged 1-27-66 through 1-29-66. It was plugged in the following manner:

1. Loaded hole w/mud laden fluid.
2. Set 15 sack cement plug from TD (6346') to 6150, covered perfs. 6195, 6211, 6221, 6233, 6239, 6266, 6275, 6284, 6295, and 6315'.
3. Set 25 sack plug @ cut off point of 5 1/2" casing (3760') half plug in and half plug out of 5 1/2" stub. (3719 to 3816')
4. Set 25 sack plug @ base of salt (3150 to 3069').
5. Set 25 sack plug @ (2138 to 2059) half in and half out of 8 5/8" csg.
6. Set 10 sack plug @ ground level to 30' w/dry hole maker.
7. Filled pits and cellar, cleaned location of all equipment & debris. This location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED CD Robertson TITLE District Clerk DATE 3-24-66
APPROVED BY John W. Runyan TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

119988 MAR 11 11 24 AM '88

MAR 11 11 24 AM '88

119988

11

119988 MAR 11 11 24 AM '88

119988 MAR 11 11 24 AM '88

119988 MAR 11 11 24 AM '88

119988 MAR 11 11 24 AM '88

11

11

119988 MAR 11 11 24 AM '88

119988 MAR 11 11 24 AM '88

119988

119988

11