

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION D. C. C.

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

101-150-1000  
JAN 7 1 31 PM '66

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
**E 9781**

7. Unit Agreement Name

8. Farm or Lease Name  
**State CG**

9. Well No.  
**1**

10. Field and Pool, or Wildcat  
**Undesignated**

12. County  
**Lea**

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Cities Service Oil Company</b>	8. Farm or Lease Name <b>State CG</b>
3. Address of Operator <b>P.O. Box 69 - Hobbs, New Mexico 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>P</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>30</b> TOWNSHIP <b>16S</b> RANGE <b>37E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undesignated</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3821 DF</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**We propose to plug the above well in the following manner:**

1. Load hole w/mud laden fluid.
2. Set 15 sack cement plug @ TD (6346') to cover perfs. 6195, 6211, 6221, 6233, 6239, 6266, 6275, 6284, 6295, and 6315.
3. Set 25 sack cement plug @ cut point of 5 1/2" csg. (3800') half of plug in and half out of stub.
4. Set 25 sack cement plug @ base of salt (3150')
5. Set 25 sack cement plug, half in and half out of 8 5/8" csg. set @ 2099'
6. Set 10 sack cement surface plug w/4" marker extending 4' above ground to designate P & A location.
7. Clean location of all equipment and debris, fill pits and cellar.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Robertson TITLE District Clerk DATE 1-7-66

APPROVED BY  TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: