

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILZ	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
11856

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	6. Farm or Lease Name Pan American 7 State
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>2324</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>7</u> TOWNSHIP <u>16-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat <u>PxA Mesa Verde</u>
15. Elevation (Show whether DF, RT, GR, etc.) 4376 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 5-5-82. Squeezed perms 3336-46 with 25 sacks of cement. Cut 2-7/8" casing at 600'. Spotted 65 sacks of cement from 600' to 341'. Pulled tubing. WOC 12 hours. Spotted 10 sack plug from 60' to surface. Welded on cap. Installed PxA marker and moved out service unit 5-6-82.

0+4-NMOCD,H 1-HOU 1 -W. Stafford,HOU 1-DMF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 8-5-82  
APPROVED BY David Catano TITLE OIL & GAS INSPECTOR DATE AUG 17 1983  
CONDITIONS OF APPROVAL, IF ANY: