

STANDARD OIL COMPANY OF TEXAS

3610 Avenue S - Snyder, Texas

February 9, 1968

New Mexico Oil Conservation Commission

Hobbs, New Mexico 88240

Attention: Mr. Ramsey


Dear Sir:

Attached are corrected copies of form C-103 for the State 22 No. 1 well.

The original C-103 submitted January 30, 1968 is in error. Please note that on the cementing affidavit attached to the original C-103 cement plugs were set across and above perforations 9722-9905, at $5\frac{1}{2}$ " stub at 7500', at top of Glorieta 5860', base of 8-5/8" casing at 4500', at stub of 8-5/8" casing, at base of surface casing (381'), and in top of surface as requested by your office.

We regret the error in the original C-103. If additional information is desired, please advise.

Yours very truly,


C. F. Kirkvold

District Production Superintendent

BD/cz

Attachment

THE UNIVERSITY OF CHICAGO



1. *Journal of the American Medical Association*, 1997; 277: 1033-1038.