

Form 3160-5
(November 1983)
(Formerly 9-331)

U. S. CIVIL COMMISSION
UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different interval.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-0315712

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Free

7. UNIT AGREEMENT NAME

Maljamar Grayburg Unit

8. FARM OR LEASE NAME

9. WELL NO.

39

10. FIELD AND POOL, OR WILDCAT

Maljamar (GB/SA)

11. SEC., T., R., W., OR BLK. AND
SURVEY OR AREA

Sec. 9, T17S, R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Chevron U.S.A. Inc.

3. ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit G, 1980 FNL and 1980 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, ST, CR, etc.)

4096

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work performed: 3/30 thru 4/3/89

Work stuck pipe. LDPE. Set 5½" CIBP at 3770'. Load csg w/35bbbls FW and attempt to tst. Isolate casing leak f/73' to 650'. Circulate well w/ P&A mud and spot 5sx C neat on top of CIBP w/cmt back to 3720'. PUH to 2230', spot 25sx C neat inside csg f/2230' to 1978'. Perf 5½" casing w/4holes at 1107'. GIH w/pkr to 1014'. Pump down tbg to establish IR through perfs, broke circ out csg annulus. Rlse pkr, POH. TIH w/ CICR and set at 1014'. Mix and pmp 300sx C1 C neat. Circ. 20sx cmt to pit. Sting out CICR. Mix and pmp additional 100sx cement. Fill up 5½" csg above CICR and circ 10sx to pit. ND BOP & NUWH, release well to production dept as TA'd.

APPROVED FOR 12 MONTH PERIOD

ENDING 4/6/90

18. I hereby certify that the foregoing is true and correct

SIGNED L. K. Eganore

TITLE Technical Assistant

DATE 4-5-89

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 6 1989

SJS

CARLSBAD, NEW MEXICO