

Sundry Notice
Hondo Oil & Gas Co.
Eidson "A" SWD #3
Page -2-

7/27/89 Displaced annulus with 221 bbls. fresh water w/PF-40
corrosion inhibitor. Tested annulus to 500 psi for
30 min. - held okay. Rigged down.

8/02/89 Returned well to SWD service.