

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

Aug 11 2 47 PM '67
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6517	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name NA
2. Name of Operator SOUTHWEST PRODUCTION CORPORATION		8. Farm or Lease Name MONTIETH STATE
3. Address of Operator P. O. BOX 936 = ROSWELL, NEW MEXICO 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> , <u>1300</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>19</u> TOWNSHIP <u>16S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat E. LOVINGTON
15. Elevation (Show whether DF, RT, GR, etc.) 3859 DF		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OF ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Completion data

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

Rigged up to complete well on 7/29/67.

Drilled out DV tool and washed hole to TD of 11,302. Perforated from 11,210 - 20, and 11,234 - 44 with one shot per foot.

Spotted acid across perforations and treated with 2000 gallons of 15% low surface tension acid.

Swabbed load back. Well flowing approximately 25 bbls. of oil per hour. Shut-in to finish hook-up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter Clements, Jr. TITLE MANAGER DATE 8/7/67
WALTER CLEMENTS, JR.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6517	
7. Unit Agreement Name N/A	
8. Farm or Lease Name MONTIETH STATE	
9. Well No. 1	
10. Field and Pool, or Wildcat E. LOVINGTON	
12. County LEA	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator SOUTHWEST PRODUCTION CORPORATION
3. Address of Operator P. O. BOX 936 - - ROSWELL, NEW MEXICO 88201
4. Location of Well UNIT LETTER E 1300 FEET FROM THE WEST LINE AND 1980 FEET FROM THE NORTH LINE, SECTION 19 TOWNSHIP 16S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3859 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Re-entered well on 6/9/67.

Washed out bottom plug in surface casing (approximately 2100').
Tested to 1500#. Pressure held okay. Finished drilling plug and washed out to previous total depth (6650').

Drilled 7-7/8" hole to 11,303. Ran 5-1/2" casing N-80, 20#, to 11,302. Placed DV tool at 6275'. First stage, cemented with 375 sacks and second stage, cemented with 425 sacks. Cement on second stage contained 4% gel. First stage was salt saturated cement with 2% gel. Pressured to 2000# okay.

Job completed 7/24/67.

WCC 48 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter Clements Jr. TITLE MANAGER DATE 8/7/67
WALTER CLEMENTS, JR.

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: