

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NA-015072
2. NAME OF OPERATOR Gulf Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 670, Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		8. FARM OR LEASE NAME Peatharstone Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4055' OL		10. FIELD AND POOL, OR WELDCAT Morton Halfway
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec 12, 15-S, 34-E
		12. COUNTY OR PARISH, 13. STATE Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Plugged and Abandoned	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and record pertinent to this work.) *

10,372' TD.

Pulled rods and pump. Pumped 350 barrels of mud down tubing. Could not load hole. Set Baker CI BP at 9520'. Dumped one sack of cement on top of BP. Loaded hole with 200 barrels of mud. Cut 5-1/2" casing at 8028' and pulled casing. Spotted 25 sack cement plug from 8150' to 8038', across 5-1/2" casing stub at 8028'. Spotted 30 sack cement plug from 4650' to 4550'. Shot 8-5/8" casing at 677' and pulled casing. Spotted 50 sack cement plug from 727' to 627', across 8-5/8" casing stub at 677'. Spotted 75 sack cement plug from 400' to 300' and 44 sack cement plug from 50' to surface. Installed dry hole marker and cleaned location. Plugged and abandoned March 6, 1969.

APPROVED

OCT 14 1969

J. L. GORDON

ACTING DISTRICT ENGINEER

18. I hereby certify that the foregoing is true and correct

SIGNED ORIGINAL SIGNED BY
G. B. BORLAND

TITLE **Area Production Manager**

DATE **March 6, 1969**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

MAR

J. L. GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents, not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 O-35228

APPROVED

APPROVED

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTES AND REPORTS ON WELL

1. NAME OF OPERATOR
2. ADDRESS OF OPERATOR
3. CITY, STATE, AND ZIP
4. PHONE NUMBER
5. TITLE OF OPERATOR
6. DATE OF OPERATION
7. NAME OF WELL
8. LOCATION OF WELL
9. DEPTH OF WELL
10. METHOD OF CLOSING TOP OF WELL
11. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

12. NAME OF WELL
13. LOCATION OF WELL
14. DEPTH OF WELL
15. METHOD OF CLOSING TOP OF WELL
16. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

17. NAME OF WELL
18. LOCATION OF WELL
19. DEPTH OF WELL
20. METHOD OF CLOSING TOP OF WELL
21. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

22. NAME OF WELL
23. LOCATION OF WELL
24. DEPTH OF WELL
25. METHOD OF CLOSING TOP OF WELL
26. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

27. NAME OF WELL
28. LOCATION OF WELL
29. DEPTH OF WELL
30. METHOD OF CLOSING TOP OF WELL
31. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

32. NAME OF WELL
33. LOCATION OF WELL
34. DEPTH OF WELL
35. METHOD OF CLOSING TOP OF WELL
36. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

37. NAME OF WELL
38. LOCATION OF WELL
39. DEPTH OF WELL
40. METHOD OF CLOSING TOP OF WELL
41. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION