

O. C. COPIES RECEIVED		
DISTRIBUTION		
NTA FE		
LE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K- 3282	
7. Unit Agreement Name	
8. Farm or Lease Name	
Lea "N" State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Galjamar - Grayburg	
12. County	
Lea	

**SUNDY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	2. Name of Operator
	C. C. Fulton
3. Address of Operator	
	P.O. Box 1121 Artesia, New Mexico 88210
4. Location of Well	
UNIT LETTER <u>N</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>16 S</u> RANGE <u>32 E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	
	4293 G L

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 180' cement plug @ 3362' - 3462'  
Set cast iron bridge plug @ 2800' & dumped 10 sk cement plug top of bridge plug @ 2800'  
Cut & pulled 5 1/2" casing @ 2591'  
Set 100' cement plug in & out of 5 1/2" stub @ 2640' - 2540'  
Set 100' cement plug top of salt @ 1700'  
Set 100' cement plug across 9 5/8 shoe @ 357'  
Set 10' cement plug @ surface  
Set regulation marker  
Heavy mud between all plugs  
Cleaned location & back filled pit

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Owner</u>	DATE <u>5-16-75</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL &amp; GAS COMMISSION</u>	DATE <u>JUN 12 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		