

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG5379	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Adobe Oil Company	8. Farm or Lease Name Lovelady State
3. Address of Operator 601 Wilkinson-Foster Bldg., Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER M , 660 FEET FROM THE west LINE AND 860 FEET FROM THE south LINE, SECTION 32 TOWNSHIP 16-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4221.7' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 10/21/70 with Lohmann Well Service and Helco reverse rig. Ran 12-1/4" bit and cleaned hole to 1008' which was top of 8-5/8" casing that had been shot off. Ran 7-3/4" mill to 1071'. Mill went outside of 8-5/8" casing. Shut in for period 10/25/70 to 10/27/70. Set 25 sx plug from 1008-973', 25 sx plug from 360-325', 10 sx plug at surface. Set marker. Finished clean up 11/6/70 and completed plugging and abandonment of well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *M. D. Page* TITLE Vice President DATE 11/10/70
APPROVED BY *John W. Runyan* TITLE Geologist DATE DEC 8 1970
CONDITIONS OF APPROVAL, IF ANY: