

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-4199	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator GULF OIL CORPORATION <i>Chevron USA Inc.</i>		8. Farm or Lease Name Eddy-Lea State (NCT-A)
3. Address of Operator P.O. Box 670, Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> <u>1990</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Undes. San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4309' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Pull tbg. Set CIBP @ 4650' & cap w/35' cmt plug. Circ hole w/101 bbls abandonment mud. Spot 100' cmt plug from 1250' to 1150'. Perf 5 1/2" csg w/(4) 1/2" strip shots @ 900'. Set cmt rtnr @ 800'; circ 5 1/2" & 8-5/8" annulus w/130 sx Class "C" cmt + 2% CaCl₂ to surf. Set cmt plug from 100' to surf. Install dry hole marker; clean & clear location.

Will notify when location is ready for inspection.

Work performed 7-30-79 thru 8-2-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. B. Sikes, Jr. TITLE Area Engineer DATE 8-3-79

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE SEP 10 1986
CONDITIONS OF APPROVAL, IF ANY: