to Appropriate District Office		Mexico Resources Department	Form C-103 Revised 1-1-89
DISTRICT P.O. Box 1980, Hobbs, NM 88240	Box 1980, Hobbs, NM 88240 P.O. Box 2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	xo 87504-2088	30-025-22062 5. Indicate Type of Lease
DISTRICT III			STATE STATE
1000 Rio Brazos Rd., Aztec, NM 8741			6. State Oil & Gas Lease No. V-3999
(DO NOT USE THIS FORM FOR DIFFERENT RE (FORM	OTICES AND REPORTS ON W PROPOSALS TO DRILL OR TO DEEPI SERVOIR. USE "APPLICATION FOR F M C-101) FOR SUCH PROPOSALS.)	EN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
I. Type of Well: Of OL OAS WELL WELL	Х отнак		Union AQZ State
2. Name of Operator YATES PETROLEUM CORP	ORATION		8. Well No.
3. Address of Operator			9. Pool name or Wildcat
105 South 4th St., A 4. Well Location	rtesia, NM 88210		Kemnitz Morrow
	ek Appropriate Box to Indicate NTENTION TO: PLUG AND ABANDON CHANGE PLANS	SUB REMEDIAL WORK COMMENCE DRILLING	SEQUENT REPORT OF:
PULL OR ALTER CASING]	CASING TEST AND CE	
DTHER:] OTHER: <u>Acidize</u>	perforations X
12 Describe Proposed or Completed Or	verstions (Clearly state all pertinent details	and give pertinent dates inclu	ding estimated date of starting any proposed
<pre>10% iron control ac down. Rigged down Shut well in. 8-9-97 - Bled well 8-10-11-97 - Bled w out tubing. Nipple TOOH. TIH with pac 1500 psi. Swabbing</pre>	treesaver. Acidized pe id with 25% methanol wi treesaver. Opened well down to pit. Swabbed a ell down. Loaded tubir d up BOP. Picked up 3-	erforations 13072 ith 1500 scf/bbl and flowed well and flowed. Shut ng with 66 bbls b -1/2" joint of tu off tool and tubb Shut well in.	2-13136' (Morrow) with 3000 gall N2 (down 2-7/8" tubing). Bled to pit for cleanup. Swabbed. well in.
work) SEE RULE 1103. 8-8-97 - Rigged up 10% iron control ac down. Rigged down Shut well in. 8-9-97 - Bled well 8-10-11-97 - Bled w out tubing. Nipple TOOH. TIH with pac 1500 psi. Swabbing 8-12-97 - Released I hereby certify that the information above in SHONATURE	treesaver. Acidized pe id with 25% methanol wi treesaver. Opened well down to pit. Swabbed a ell down. Loaded tubir d up BOP. Picked up 3- ker with 1.875" XL on/c (zones 13072-13316'). well to production depa	erforations 13072 ith 1500 scf/bbl and flowed. Shut ng with 66 bbls b -1/2" joint of tu off tool and tubi Shut well in. artment.	2-13136' (Morrow) with 3000 gall N2 (down 2-7/8" tubing). Bled to pit for cleanup. Swabbed. well in. orine. Released packer. Revers bing. Released RBP at 13175'. Ing. Set packer and tested to
work) SEE RULE 1103. 8-8-97 - Rigged up 10% iron control ac down. Rigged down Shut well in. 8-9-97 - Bled well 8-10-11-97 - Bled w out tubing. Nipple TOOH. TIH with pac 1500 psi. Swabbing 8-12-97 - Released I hereby certify that the information above in SKONATURE	treesaver. Acidized per id with 25% methanol wit treesaver. Opened well down to pit. Swabbed a ell down. Loaded tubir d up BOP. Picked up 3- ker with 1.875" XL on/c (zones 13072-13316'). well to production depa a true and complete to the best of my knowledge of the sector of the best of	erforations 13072 ith 1500 scf/bbl and flowed. Shut ng with 66 bbls b -1/2" joint of tu off tool and tubi Shut well in. artment.	2-13136' (Morrow) with 3000 gall N2 (down 2-7/8" tubing). Bled to pit for cleanup. Swabbed. well in. orine. Released packer. Revers bing. Released RBP at 13175'. ing. Set packer and tested to 'echnician DATE Aug. 28, 1997 TELEPHONE NO. 505/748-1
work) SEE RULE 1103. 8-8-97 - Rigged up 10% iron control ac down. Rigged down Shut well in. 8-9-97 - Bled well 8-10-11-97 - Bled w out tubing. Nipple TOOH. TIH with pac 1500 psi. Swabbing 8-12-97 - Released I hereby certify that the information above in SHONATURE SHONATURE Rusty K10	treesaver. Acidized per id with 25% methanol wit treesaver. Opened well down to pit. Swabbed a ell down. Loaded tubir d up BOP. Picked up 3- ker with 1.875" XL on/o (zones 13072-13316'). well to production depa well to production depa function departments well to product of my knowledge a	erforations 13072 ith 1500 scf/bbl and flowed. Shut ng with 66 bbls b -1/2" joint of tu off tool and tubi Shut well in. artment.	2-13136' (Morrow) with 3000 gall N2 (down 2-7/8" tubing). Bled to pit for cleanup. Swabbed. well in. orine. Released packer. Revers bing. Released RBP at 13175'. Ing. Set packer and tested to
work) SEE RULE 1103. 8-8-97 - Rigged up 10% iron control ac down. Rigged down Shut well in. 8-9-97 - Bled well 8-10-11-97 - Bled w out tubing. Nipple TOOH. TIH with pac 1500 psi. Swabbing 8-12-97 - Released I hereby certify that the information above in signature Musty Klasses TYPE OR FRINT NAME Rusty Klasses	treesaver. Acidized per id with 25% methanol wit treesaver. Opened well down to pit. Swabbed a ell down. Loaded tubir d up BOP. Picked up 3- ker with 1.875" XL on/c (zones 13072-13316'). well to production depa a true and complete to the best of my knowledge of the second by ein	erforations 13072 ith 1500 scf/bbl and flowed well and flowed. Shut ng with 66 bbls b -1/2" joint of tu off tool and tubi Shut well in. artment. mdbelia.	2-13136' (Morrow) with 3000 gall N2 (down 2-7/8" tubing). Bled to pit for cleanup. Swabbed. well in. orine. Released packer. Revers bing. Released RBP at 13175'. ing. Set packer and tested to 'echnician DATE Aug. 28, 1997 TELEPHONE NO. 505/748-1

50