

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 17 10 33 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole	7. Unit Agreement Name
2. Name of Operator Cities Service Oil Company	8. Farm or Lease Name Nichols B
3. Address of Operator Box 69 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1900 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 15S RANGE 35E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3975 DF	12. County Lee

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TO 10681 Line and Chart - P&T 10636. We propose to plug and abandon the above well in the following manner:

1. Set 50 sack cement plug across claco perfs. (squeeze 40 sacks into perfs. and 10 sack cement plug across perfs. (10545-10609).
2. Cut and pull 5 1/2' casing @ 9102. Set 25 sack cement plug (half in and half out) of 5 1/2' casing stub @ 9102.
3. Set 25 sack cement plug across top of glorieta @ 6303-6222.
4. Set 25 sack cement plug (half in and half out) of 8 5/8' casing @ 4804-4764.
5. Set 10 sack cement surface plug @ 30-0 with a 4' marker extending 4' above ground level to designate a P & A location.
6. Fill pits and cellar. Clean location of all debris.

The above plugging proposal was verbally approved by your Mr. Eric Engbrecht on 9-6-67.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED ORIGINAL SIGNED C. D. ROBERTSON	TITLE District Clerk	DATE 9-13-67
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		