

NO. OF COPIES RECEIVED	
DISTRIBUTION	
STATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMCCC
1-Midland
1-Pile

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> For <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - M" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY	8. Farm or Lease Name STATE "PS"
3. Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO 88240	9. Well No. 11
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE WEST LINE, SECTION 32 TOWNSHIP 16-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat LOVINGTON QUEEN
15. Elevation (Show whether DF, RT, GR, etc.) 3601 GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon this well as follows:

1. Set CIBP @ 3750' and dump 35' of cement on top.
2. Circulate hole with 9.2# brine mixed with 25 sks./ 100 bbl. salt gel.
3. Place 100' cement plug with top @ 1950'. (Top of salt @ 1997'.)
4. Place 10 sk. cement plug @ surface.
5. Set P/A Marker and clear off location.

No casing to be pulled, since cement was circulated on all strings.

THE COMMISSION MUST BE NOTIFIED 21
DAYS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

THE COMMISSION MUST BE NOTIFIED 24
DAYS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-102
TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. L. Wade: C. L. Wade TITLE AREA SUPERINTENDENT DATE JANUARY 14, 1976

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 15 1976

OIL CONSERVATION COMM.
HOBBBS, R. M.