OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

July 28, 1968

King Resources Company Security Life Building Denver, Colorado 80202

Dear Sir:

The Commission finds that your P & A well the Shell State No. 1, located in Unit O, Section 32, T 158 - R 32E, was reported ready for surface inspection on July 1, 1968. Subsequent inspection on July 19, 1968 found the location not to be ready.

Condition of location was as follows:

- 1. Pits have not been leveled.
- 2. Celler is open.
- 3. Junk on location.

Your plugging bond cannot be released until the above work is completed. Please notify us only when work is done.

Very truly yours,

OIL CONSERVATION COMMISSION

John W. Runyan Geologist, District 1

JWR/pdf ee: MNOCC Hohn W. Runyan

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

1015 28, 1908

Norg Resources longeny occulity Life Liding Denser, Colorado Su200

12 18 M

The commission finds that your F & A self whe Scell State Storing moded in Unit G, Section 32, T 195 - R 32E, was reported ther serface inerestion on only L, 1965. Successent inspectron or roly 19, 1966 found the location not to be ready.

sandlers af location was as follows:

.bsievel need ion even aste

.requisiter is

. DoltBord no master R

your plo ging band came? Le released out it the derve w co to completed. Flasse nortly an **only whe**n when whe is draw.

ALL IN STRUCT 22.09

OLD CORSERVATEON OF THESE OF

John W. Janyon G**eologis**ti Banako (

1711-966-11-144 ##Y25-146-146-144