

Double "C" Enterprises
P.O. Box 147
Lovington, N.M. 88260

We have examined all available geologic data and all available engineering data and find no evidence of open faults or any other hydrolic connection between the disposal zone and any underground source of drinking water.

Roland E. Caudill

Partner, May 31, 1984