

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG 4765	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator PENNZOIL COMPANY		8. Farm or Lease Name Aztec State
3. Address of Operator P.O. Drawer 1828, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>16-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat Lovington Penn NE
15. Elevation (Show whether DF, RT, GR, etc.) 3844.2 GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/9/80 RU unit, fished hydraulic pump.
6/10/80 Displaced hole w/produced wtr. tagged BTM at 11,475'. POOH w/TBG. WIH w/paraffin knife.
6/11/80 Ran sand pump on sand line to clean fill. Could not clean out
6/12/80 Ran hydrostatic bailed on TBG. Could not clean fill.
6/13/80 Perforated the straw zone at 11,431-38, 44-48, 52-56, w/1 JSPF (18 holes)
Tested TBG in hole to 4500#. Set pwr at 11,419.
6/14/80 Acidized new perfs 11,431-11,456 w/3500 gals 15%. Had communication with old straw perfs above at 11,336-11,386.
6/16/80-6/18/80 SWB back all load. Very little trace of oil.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. V. Guller TITLE Operation Engineer DATE 6/19/80

APPROVED BY Jerry Seaton TITLE DATE JUN 22 1980

CONDITIONS OF APPROVAL, IF ANY: