

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
-

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
	-

2. Name of Operator	8. Farm or Lease Name
Charles B. Read	Alexander

3. Address of Operator	9. Well No.
P. O. Box 2126, Roswell, New Mexico 88201	1

4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM	Wildcat

THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>15S</u> RANGE <u>36E</u> NMPM.	
--	--

15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3902.5' GR	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
--

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
--

Set a 25 sx cement plug at 10,560' to 10,310'
Cut 5 1/2" csg at 5830'
Pull 5830' of 5 1/2" csg
Cut and remove 1725' of 8 5/8" csg
Set a 25 sx cement plug at 5840' to 5765'
Set a 25 sx cement plug at 4910' to 4845'
Set a 25 sx cement plug at 1769' to 1710'
Set a 25 sx cement plug at 1190' to 1149'
Set a 25 sx cement plug at 458' to 417'

Left top hole open for farmer

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John W. Runyan</u>	TITLE <u>Agent</u>	DATE <u>July 19, 1968</u>
------------------------------	--------------------	---------------------------

APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		