

OIL CONSERVATION DIVISION
P.O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S. L.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. A 1320
7. Unit Agreement Name
8. Form or Lease Name State A-1320
9. Well No. 1
10. Field and Pool, or Wildcat Shoe Bar East Devonian
12. County Lea

SUMMARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A WELL BACK TO A DIFFERENT RESERVOIR.
USE THE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Jake L. Hamon
3. Address of Operator 611 Petroleum Building, Midland, Texas 79701
4. Location of Well UNIT LETTER B 510 FEET FROM THE North LINE AND 1980 FEET FROM THE East CORNER SECTION 31 TOWNSHIP 16 S RANGE 36 E NMPAL.

15. Elevation (Show whether DE, RT, GR, etc.)
3960.3' K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Circulate hole with 10# mud and pull tubing out of hole.
2. Set bridge plug in 5-1/2" casing at 12,900' and dump 35' (4 sacks) of cement on plug.
3. Set cement plugs as following:
 - a. 100' (35 sacks) in and out of the 5-1/2" casing stub. Tag Plug.
 - b. If the 5-1/2" casing is pulled below the top of the Glorietta Sand at 6355', set a 100' (35 sack) cement plug at the top of the Glorietta.
 - c. 150' (60 sacks) in and out of the base of 9-5/8" casing from 4300' back to 4150'. Tag plug.
 - d. 100' (75 sacks) in and out of the 9-5/8" casing stub.
 - e. 100' (75 sacks) at top of salt at 2136' if exposed.
 - f. 130' (100 sacks) in and out of the base of the 13-3/8" surface casing from 465' back to 335'. Tag plug.
 - g. 10' (10 sacks) in the top of the 13-3/8" casing and set a 4" OD permanent marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE CHOP TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cecil H. Barton TITLE Production Engineer DATE 10/28/81

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: