

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE O. G. C.
May 23 11 56 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- DRY HOLE	7. Unit Agreement Name
2. Name of Operator MONTIETH COMPANY	8. Farm or Lease Name MONTIETH
3. Address of Operator 101 North Maricopa, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 16-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3906' BT	12. County Lee

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled to a total depth of 11,330' and found to be a dry hole.
The well was plugged and abandoned as follows: filled hole w/100 sand, cement plugs
as follows: 25 sx 11,330-11,236', 25 sx 9468-9369', 25 sx 8181-7884', 25 sx 6290-6193',
25 sx 4818'-4706'.

Shot off 8-5/8" casing at 1770' and pulled.

Set cement plugs as follows: 25 sx 3518-3406', 25 sx 2112-2020', 25 sx 365-328',
10 sx at surface.

4" x 6" marker w/location marked thereon in surface pipe.

Filled pits and cleaned up location. Now ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. W. WITTE TITLE Dist. Prod. Supt. DATE 5/19/69

APPROVED BY John W. Runyan TITLE Asst. Dir. DATE JUN 11 1969
CONDITIONS OF APPROVAL, IF ANY: