NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	Ι	
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

DISTRIBUTION  SANTA FE  NEW MEXICO OIL CONSERVATION COMMISSION  AFR 23 12 02 PM '59  U.S.G.S.	Supersedes Old		
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	·		
FILE APR 23 12	C-102 and C-103 Effective 1-1-65		
	=11000000 [4]-100		
U.S.G.S. 12 02 14 160	5a. Indicate Type of Lease		
LAND OFFICE	State Y Fee		
OPERATOR	5. State 121 & Gus Lease No.		
OPERATOR			
	K 6806		
SUNDRY NOTICES AND REPORTS CHA WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DE L. OR TO DEEPER OR PLUS SOCK TO A LISTERSANT RUSSALVIN.  USE "APPLICATION FOR PERMIT S." FORM CITICAL FOR SIGHT SERVEYSALS.			
I.  OIL GAS WELL OTHER-	7. Unit Agréement Name		
2. Name of Operator	8. Farm or Lease Name		
Donnaril United Inc	State "16"		
Pennzoil United, Inc. 3. Address of Operator	9. Well No.		
	,		
P. O. Drawer 1828 - Midland, Texas 79701	10. Field and Pool, or Wildcat		
UNIT LETTER M, 660 FEET FROM THE <b>SOUTH</b> LINE AND 660 FEET	T FROM Undesignated		
THE West LINE, SECTION 16 TOWNSHIP 16-S RANGE 37-E	NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
3809' GL	Lea		
Check Appropriate Box To Indicate Nature of Notice, Report of	or Other Date		
•			
NOTICE OF INTENTION TO:			
NOTICE OF INTENTION TO: SUBSEQ	UENT REPORT OF:		
	7		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON COMMENCE DRILLING OPNS. X  PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB X	ALTERING CASING PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  OTHER	ALTERING CASING  PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc	ALTERING CASING  PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  OTHER	ALTERING CASING  PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103.	ALTERING CASING  PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69  Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'.	ALTERING CASING  PLUG AND ABANDONMENT  Luding estimated date of starting any proposed		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1703.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'. 4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla	ALTERING CASING  PLUG AND ABANDONMENT  Cluding estimated date of starting any proposed  USS "H" 6% gel + 150 sx		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'. 4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu	ALTERING CASING  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  USS "H" 6% gel + 150 sx  Flated 0.K.		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'.  4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min	ALTERING CASING  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'. 4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min 4-9-69 Drilled 11" hole to 4355'. Ran 8 5/8" OD, 24# & 32# csg	ALTERING CASING  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  ISS "H" 6% gel + 150 sx  Ilated 0.K.  Tested 0.K.  J. to 4355' Cemented		
Perform remedial work  Temporarily abandon  Pull or alter casing  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69  Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'.  4-3-69  Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69  After 19 hrs WOC, tested casing w/1,000# for 30 min	ALTERING CASING  PLUG AND ABANDONMENT  Fluding estimated date of starting any proposed  ISS "H" 6% gel + 150 sx  Ilated 0.K.  Tested 0.K.  J. to 4355' Cemented		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'.  4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min 4-9-69 Drilled 11" hole to 4355'. Ran 8 5/8" OD, 24# & 32# csg w/350 sx Class "H" 50/50 posmix 6% gel w/11# salt per s w/5# salt per sack. Plug down @ 8:45 P.M.	ALTERING CASING PLUG AND ABANDONMENT  Soluting estimated date of starting any proposed  ALTERING CASING PLUG AND ABANDONMENT  Solution of the starting any proposed  ALTERING CASING PLUG AND ABANDONMENT  Solution of the starting any proposed  ALTERING CASING PLUG AND ABANDONMENT  ALTERING CASING PL		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'.  4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min 4-9-69 Drilled 11" hole to 4355'. Ran 8 5/8" OD, 24# & 32# csg w/350 sx Class "H" 50/50 posmix 6% gel w/11# salt per s w/5# salt per sack. Plug down @ 8:45 P.M.	ALTERING CASING  PLUG AND ABANDONMENT  Cluding estimated date of starting any proposed  ALSS "H" 6% gel + 150 sx  Ilated 0.K.  Tested 0.K.  J. to 4355' Cemented  Sack + 150 sx Class "C"		
Perform Remedial work  Temporarily abandon  Pull or alter casing  Other  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) see rule 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'. 4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min 4-9-69 Drilled 11" hole to 4355'. Ran 8 5/8" OD, 24# & 32# csg w/350 sx Class "H" 50/50 posmix 6% gel w/11# salt per s w/5# salt per sack. Plug down @ 8:45 P.M.  4-10-69 Ran temperature survey. Top cement 3050'. After 28 hrs	ALTERING CASING  PLUG AND ABANDONMENT  Soluting estimated date of starting any proposed  Plus "H" 6% gel + 150 sx  Plated 0.K.  Tested 0.K.  Tested 0.K.  To 4355' Cemented  Back + 150 sx Class "C"		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'.  4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min 4-9-69 Drilled 11" hole to 4355'. Ran 8 5/8" OD, 24# & 32# csg w/350 sx Class "H" 50/50 posmix 6% gel w/11# salt per s w/5# salt per sack. Plug down @ 8:45 P.M.	ALTERING CASING  PLUG AND ABANDONMENT  Soluting estimated date of starting any proposed  Plus "H" 6% gel + 150 sx  Plated 0.K.  Tested 0.K.  Tested 0.K.  To 4355' Cemented  Back + 150 sx Class "C"		
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  4-2-69 Spudded 17 ½" hole @ 8:00 P.M Drilled to 348'. 4-3-69 Ran 13 3/8" OD, 48# csg. to 348'. Cemented w/200 sx Cla Class "H" 2% CaCl. Plug down @ 8:45 A.M Cement circu 4-4-69 After 19 hrs WOC, tested casing w/1,000# for 30 min 4-9-69 Drilled 11" hole to 4355'. Ran 8 5/8" OD, 24# & 32# csg w/350 sx Class "H" 50/50 posmix 6% gel w/11# salt per s w/5# salt per sack. Plug down @ 8:45 P.M.  4-10-69 Ran temperature survey. Top cement 3050'. After 28 hrs	ALTERING CASING  PLUG AND ABANDONMENT  Soluting estimated date of starting any proposed  Plus "H" 6% gel + 150 sx  Plated 0.K.  Tested 0.K.  Tested 0.K.  To 4355' Cemented  Back + 150 sx Class "C"		

18, I hereby certify that the information above is true and complete	te to the be	est of my knowledge and helief.		
GIGNED Jeashurs	TITLE	Duilling Cunamintendent	DATE	4-22-69
PPROVED BY AND MILES	T!TLE_		DATE	
ONDITIONS OF APPROVAL, I ANY:	•			