

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Clinton Oil Company	8. Farm or Lease Name Montieth "C"
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>1</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>16</u> RANGE <u>36</u> NMPM.	10. Field and Pool, or Wildcat N.E. Lovington (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 3846' D.F.	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set a CBP w/20' cement on top at 11,000'.
2. Set a 25 sx cement plug at 5 1/2 casing stub at 10,050'.
3. Set a 25 sx cement plug at top of Wolfcamp at 9782'.
4. Set a 25 sx cement plug at top of Abo at 8257'.
5. Set a 25 sx cement plug at top of Glorietta at 6224'.
6. Set a 25 sx cement plug at 8-5/8 casing shoe at 4400'.
7. Set a 25 sx cement plug at 8-5/8 casing stub at 1120'.
8. Set a 25 sx cement plug at 13-3/8 casing shoe at 400'.
9. Set a 10 sx cement plug at surface with marker.
10. Well was loaded with mud-laden fluids.
11. Well was plugged and abandoned on 7/10/71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 7/12/71

APPROVED [Signature] TITLE OIL & GAS INSPECTOR DATE 7/12/71

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 1 1971

OIL CONSERVATION COMM.  
HOUSTON, TEX.