

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
A-1720	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ <u>Dilig</u>	7. Unit Agreement Name
2. Name of Operator <u>Humble Oil & Refg Co</u>	8. Farm or Lease Name <u>New Mexico CT State</u>
3. Address of Operator <u>Box 1600 - Midland, Texas 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>N</u> LINE AND <u>510</u> FEET FROM THE <u>E</u> LINE, SECTION <u>31</u> TOWNSHIP <u>16-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat <u>ShoeBar - E Devonian</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3951 DF</u>	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Completion Attempt ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

R.V. and perf 4 1/2" csq from 13033 to 13036'. Test well. Recovered 100% water. Set wireline C.I. Bridge Plug @ 12990' and topped w/ 20' of cmt to 12,970'. Temp Survey indicated top cmt @ 7700' - cut off 4 1/2" csq @ 7700' and recovered same. Cut off 8 7/8" csq @ 2650' and pull same. R.V. and plug well. Set cmt plugs from 7200-7000' w/ 50 sax, 6300-6200' w/ 40 sax, 4900-4700 w/ 75 sax, 4250-4200 w/ 30 sax, 2700-2600' w/ 60 sax, 2100'-2000' w/ 40 sax, 425-390' w/ 30 sax across str csq shoe @ 402'. Top Plug 25'-0' w/ 10 sax. Installed dry hole marker and Clean Location. Well P4A, final Report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Unit Head

DATE 1/17/70

APPROVED BY John W. Runyan

TITLE Geologist

DATE MAY 5 1971

