

32. Acid, Shot, Fracture, Cement Squeeze. Etc.

Perforated 4128, 4148, 4155, 4167, 4170 w/16.45
JSPF Treated perfs from 4128 to 4170
w/ 1000 gals 15% LSTNE --- let CIBP at
4110

Perforated 4068, 4066, 4064, 4062, 4050,
3934, 3932, 3930, 3928, 3926,
3829, 3824, 3814, 3806, 3803, 3798, 3782,
and 3778

Treated perfs 4068 to 3926 w/7000 gals 15% LSTNE
and 110 gals TH-763 chemicals.

Treated Perfs 3829 to 3778 w/1000 gals mud acid,
55 gals TH-763 plus 20,000 gal water
30,000 # sand frac.

Squeezed Perfs 4068' to 4062' w/ 50 sacks
Class 'C' cement

Perforated 4060 to 4062 w/ 2 (.50") JSPF
treated Perfs 4060-4062 w/ 3000 gals 15% LSTNE
followed w/ 1500 gals 28% LSTNE plus
2500 gals 15% LSTNE

Squeezed Perfs 4060-4062 w/ 68 sacks Class 'C'
cement

Perforated 4066 w/ 4 (.50") JSPF
treated 4066" w/ 3500 gals 15% XRA plus
55 gals TH-763