

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

OG 5379

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Adobe Oil Company	8. Farm or Lease Name Lovelady State
3. Address of Operator 601 Wilkinson-Foster Bldg., Midland, Texas	9. Well No. 1-Y *
4. Location of Well UNIT LETTER M , 660 FEET FROM THE south LINE AND 660 FEET FROM THE west LINE, SECTION 32 TOWNSHIP 16-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4221' Gr.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

***Revised to correct well number on report filed 11/3/71, and to replace same.**

Adobe Oil Company proposes to P&A the above well. We plan to spot a 50 sx plug over the perforations from 4480-4485'. We will then cut off the 9-5/8" casing at its free point. A 25 sx plug will then be set in top of 9-5/8" casing, a 45 sx plug in and out of 13-3/8" casing at 315', and a 10 sx plug at surface. A marker and the cleanup will complete the P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Vice President** DATE **11/9/71**

APPROVED BY *[Signature]* TITLE **SUPERVISOR DISTRICT I** DATE **NOV 11 1971**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

11-1-1971

OIL CONSERVATION COMM.
HOBBBS, R. H.