

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT L" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator BTA Oil Producers		8. Farm or Lease Name Mathis 7114 JV-D
3. Address of Operator 104 South Pecos, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER "L" 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 15-S RANGE 35-E NMPM.		10. Field and Pool, or Wildcat Chambers-Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3950' GL, 3960' KB		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging procedure:

Set CIBP @ 10,500' w/3 sx (35') cmt on top
Cut & pull 5½" csg (Top cmt @ 8812')
35 sx @ 5½" stub
35 sx @ 8192' (Wolfcamp)
35 sx @ 6843' (Clearfork)
35 sx @ 6232' (Glorietta)
50 sx @ 4750' (8-5/8" shoe)
Cut & pull 8-5/8" csg
50 sx @ 8-5/8" stub
50 sx @ 400' (12-3/4" shoe)
10 sx @ surface
Mud laden fluid between plugs
Install dry hole marker per NMOCC regulations
Verbal approval by John Runyan 4-26-72

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. A. Boyer TITLE Production Clerk DATE 4/27/72

APPROVED BY Joe D. Ramsey TITLE Dist. 1, Supv. DATE MAY 1 1972
CONDITIONS OF APPROVAL, IF ANY: