NO. OF COPIES RECEIVED					Ferm C-10	3	
DISTRIBUTION				•	Supersede.		
SANTA FE		NEW MEXICO OIL	CONSERVATI	ON COMMISSION	C+102 and Effective		
FILE	:						
U.S.G.S.					5a. Indicate T	ype of Lease	
LAND OFFICE					State	Fee K	
OPERATOR					5. State Cil &	Gas Lease No.	
	SUNDRY NOTIC	ES AND DEDOOT	C ON WELL C		777777		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR FERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
l.			ON SOCH PACES	, r. 5 .)	7. Unit Agreer	nent Name	
OIL X W	AS OTHER-						
2. Name of Operator						ase Name	
BTA Oil Producers					Mathie	Mathis 7114 JV-D	
3. Address of Operator						9. Well No.	
104 South Pecos, Midland, Texas 79701					1		
4. Location of Well					10. Field and	Pool, or Wildest	
UNIT LETTER "L" , 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM					1	Wolfcamb	
					FROM		
West	35	7	5-5	35-E			
THE TYCKS C	LINE, SECTION35	TOWNSHIP	RA	NGE	NMPM. ()		
mmmm		15 Flavation (Show u	hather DE RT	CR etc.	12. County	111/1/1/	
15. Elevation (Show whether DF, RT, GR, etc.)					Lea		
	Check Appropria	ite Box To Indic	ate Nature o	of Notice, Report o	or Other Data		
гои	TICE OF INTENTION	4 TO:		SUBSEQ	UENT REPORT O	F:	
PERFORM REMEDIAL WORK		PLUG AND ABANDO	N REMEDIA	AL WORK	ALI	TERING CASING	
TEMPORARILY ASANDON			COMMEN	CE DRILLING OPNS.	PLU	G AND ABANDONMENT	
PULL OR ALTER CASING		CHANGE PLANS	CASING	TEST AND CEMENT JOB	ā		
			ОТНЕ	; R			
OTHER							
17. Describe Proposed or work) SEE RULE 110	Completed Operations (Cl	learly state all pertine	ent details, and p	give pertinent dates, inc	luding estimated date	of starting any propos	
,							
12-15-71	Spudded in	at 10:00 A.	M. 12-8-	71. Drilled	$1.7\frac{1}{5}$ " hole	to	
	Spudded in at 10:00 A.M. 12-8-71. Drilled $17\frac{1}{2}$ " hol 402' & ran 12-3/4" O.D., 33.38# surface casing set						
	400' w/400 sx 2% C.C. (cement circulated). Plug down						
,	400 W/400		1 Cement				
					. Prug down	•	
10 16 71	@ 5:15 P.M.	12-14-71.	Now WOC	•		•	
12-16-71	@ 5:15 P.M. After WOC 18	12-14-71. 8 hrs teste	Now WOC d casing	•		•	
	@ 5:15 P.M. After WOC 18 held OK. No	12-14-71. 8 hrs teste ow drilling	Now WOC d casing ahead.	to 800# for	30 min		
12-16-71 12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11"	12-14-71. 8 hrs teste ow drilling hole to 47	Now WOC d casing ahead. '50' & ra	to 800# for n 8-5/8" O.D	30 min		
	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 ca	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a	Now WOC d casing ahead. 50' & ra t 4750'	to 800# for	30 min		
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 ca 3:45 A.M. 13	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. N	Now WOC d casing ahead. [50] & rate 4750]	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" O.D	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 ca 3:45 A.M. 13	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cc 3:45 A.M. 13 After WOC 18	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. Name of the steet	Now WOC ed casing ahead. '50' & ra t 4750' Tow WOC. ed casing	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	
12-23-71	@ 5:15 P.M. After WOC 18 held OK. No Drilled 11" 32#, J-55 cs 3:45 A.M. 13 After WOC 18 held OK. No	12-14-71. 8 hrs teste ow drilling hole to 47 asing set a 2-23-71. N 8 hrs teste ow drilling	Now WOC d casing ahead. 50' & ra t 4750' Now WOC. d casing ahead.	to 800# for n 8-5/8" 0.D w/375 sx. P	30 min 0., 24#, 28# Plug down at	• ,	

DATE ______ 3 1972

Orig. Signed by Joe D. Ramey Dist. I, Supv.